

# GSP Operation

- 4- RTU check is there any command in the frame , if yes update output tags  
If not sync RTU time with master
- 5 – disconnect connection for next transition
- 6 – if GSP frame is for logged file ( when RTU is offline) , delete log file .

- 3 – GSP Master OPC Server check is there any command for RTU  
If yes send command on same session with Current Master Time to RTU  
If there is no command only send current master Time for time sync to RTU

